MCDONNELL DOUGLAS

Douglas Aircraft Company

15 October 1992 C1-Q6C-BI-92-320

California Regional Water Quality Control Board - Los Angeles Region 101 Centre Plaza Drive Monterey Park, CA. 91754

Attention:

Technical Support Unit

Subject:

Technical Monitoring Report: NPDES Permit No. CA0001406-Compliance File No. 6116 and NPDES Permit No. CA001414-

Compliance File No. 5999 , 3rd Quarter 1992

Gentlemen:

Douglas Aircraft Company is submitting the technical reports on self monitoring work performed according to the specifications contained in Monitoring and Reporting Program Numbers 6116 and 5999. The enclosures summarize reporting period at both the Long Beach and Torrance facilities.

All analyses were conducted by Truesdail Laboratories, Inc. of Tustin, California in accordance with the with the current EPA guideline procedures or as specified in the Monitoring Program.

Please contact the undersigned at (310) 593 - 3873, if you have any questions regarding this submittal.

"I declare under penalty of perjury that the foregoing is true and correct", executed on the 15th of October 1992.

Sincerely,

Boramy Ith

Environmental Engineer

Borony Ith

Safety, Health and Environmental Affairs

DOUGLAS AIRCRAFT CO. 19503 S. NORMANDIE AVE. TORRANCE, CA. 90502 MONITORING AND REPORTING PROGRAM NO. 5999 NPDES PERMIT NO. CAOOO1414

THIRD QUARTER - 1992

COMPLIANCE WITH STORM DRAIN EFFLUENT LIMITS

PARAMETER 	CONCENTRATION LIMITS 		 			I I I I I DISCHARGE I	
; ; ;			7/13/92	B/31/92	10/5/92	LIMITS	
pH	-	6.0-9.0	7.0	8.1	7.4	. N	
TEMPERATURE	- -	100F	80	86	76	i N	1
SUSPENDED SOLIDS	50	150	i 	· 	1 1 79	! N	1
: SETTLEABLE SOLIDS	0.1 ml/l	0.3 m1/1	1		1.5	' ! Y	!
BOD5 @ 20C	20	60	i [i 	10.2	! N	1
DIL & GREASE	10	i ! 15	i . [.	i 	I ND	i I N	!
: CHROMIUM TOTAL	0.005	0.01	; 	i .	0.015	! Y	!
! ! TOTAL WASTE FLOW-GPD !			; ! 10,450 !	; 11,650 	; 7,200 	! ! !	1 1 1

DUE TO THE LOWER FLOW RATE, A GRAB SAMPLE MAY HAVE RESULTED IN HIGHER THAN EXPECTED SETTLEABLE SOLIDS AND TOTAL CHROMIUM

REPORT

UESDAIL LABORATORIES, INC.



14201 FRANKLIN AVENUE TUSTIN, CALIF, 92680 AREA CODE 714 • 730-6239 AREA CODE 213 • 225-1564 FAX 714 • 730-6462

CLIENT: Douglas Aircraft Company

Internal Mail Code C6-59 19503 S. Normandie Avenue

Torrance, CA 90502

ATTN: Boramy Ith

REPORT DATE: October 14, 1992

RECEIVED: July 13, 1992

LABORATORY NUMBER: 54667

Water from Stormdrain Torrance Facility - 7/13/92 P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by NPDES Permit #CA0001414, July, 1992

RESULTS

Field Data

FIUW, GPD:

Temperature, OF:

pH, Units (EPA 150.1)

10,450

80

7.0

Respectfully Submitted, Truesdail Laboratories, In-

Thomas Herrin, Manager

Environmental Field Services



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

UESDAIL LABORATORIES, INC.

RESEARCH - DEVELOPMENT - TESTING



14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680 AREA CODE 714 • 730-6239 AREA CODE 213 • 225-1564 FAX 714 • 730-6462

CLIENT:

Douglas Aircraft Company

Internal Mail Code C6-59

19503 S. Normandie Avenue

Torrance, CA 90502

ATTN: I

Boramy Ith

REPORT DATE: October 14, 1992

RECEIVED: August 31, 1992

LABORATORY NUMBER: 55114

Water from Stormdrain Torrance Facility - 8/28/92 P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by NPDES Permit #CA0001414, August, 1992

RESULTS

Field Data

r⊥ow, GPD:

11,650

Temperature, OF:

86


pH, Units (EPA 150.1)

8.1

Respectfully Submitted, Truesdail Laboratories, Inc.

Thomas Herrin, Manager

Environmental Field Services



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

UESDAIL LABORATORIES, INC.

.EMISTS - MICROBIOLOGISTS - ENGINEERS DEVELOPMENT



14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680 AREA CODE 714 · 730-6239 AREA CODE 213 · 225-1564 FAX 714 • 730-6462

CLIENT:

Douglas Aircraft Company Internal Mail Code C6-59

19503 South Normandie Ave.

Torrance, CA 90502

ATTN:

Dan Palacios

REPORT DATE: October 14, 1992

RECEIVED: October 5, 1992

LABORATORY NUMBER: 55478

Water from Stormdrain, Torrance Facility

P.O. No: T & M 25998C

Third Quarter, 1992, Analysis as Required by NPDES Permit #CA0001414

RESULTS

Total Flow, GPD	3,494
Temperature, ^O F	76
pr Units (EPA 150.1)	7.4

Parameter	Method	MILLIGRAMS PE Detection Limit	R LITER Concentration
Biochemical Oxygen Demand	405.1	2.0	10.2
Chromium	200.7	0.01	0.015
Oil and Grease	413.1	6.0	ND
Settleable Solids (ml/L/hr)	160.5	0.20	1.5
Total Suspended Solids	160.2	4.0	79.0

*ND = Not detected, below detection limit

Respectfully Submitted, Truesdail Laboratories, Inc.

Thomas Herrin, Manager Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity, matter without prior written authorization from these Laboratories.